

→ An Air & Water Technologies Company

June 21, 1994

Mr. Joe Fredle U.S. Environmental Protection Agency Region 5, Emergency Response Branch 25089 Center Ridge Road Westlake, Ohio 44145



Subject:

Granville Solvents Site (GSS) Interim Response Action

Revised Groundwater Data Maps

Dear Mr. Fredle:

As you may recall from the conference call Monday, June 20, 1994, I called your attention to errors in the Draft Maps sent to you on June 14, 1994 and June 16, 1994 that contained summaries of analytical data for groundwater samples. These errors included mis-labeling acetone results as 1,1-DCE for Hydropunch^{III} sampling location HP-1.

I have taken the liberty to revise these maps (titled Hydropunch Sampling Locations and Monitoring & Temporary Well Sampling Locations) and provide you and the other recipients with copies. Please return the previously supplied maps using the enclosed self addressed postage paid envelopes.

If you have questions regarding this transmittal, please contact Mr. Gerald Myers or me.

Respectfully,

METCALF & EDDY, INC.

Michael S. Raimonde Project Hydrogeologist

Attachment

cc: Ben Pfefferle, Thompson, Hine, and Flory

Ed Hanlon, U.S. EPA Mike Anastasio, U.S. EPA Fred Myers, Ohio EPA Gerald Myers, M&E



